

February Report – Steer Point Quarry Restoration

Since the last meeting only 2680 tonnes has been brought to site in 148 loads reflecting approx. 50% of the permitted loads due to the continued poor weather and availability of suitable material.